



DUAL TRU-TRAINER[®] TRAINING IDLER

ADDENDUM:

WARNING: Only invert this trainer with its secure retention strap welded into position (see picture below).

There needs to be 1" of belt deflection for proper contact of trainer to either the clean side of the return area or carryback side of the return area.

