



Grizzly™ Screw Splice - Screw Size Guide

Final Thickness	63	65	80	85	100	180	200
19mm (3/4")						6x30mm	6x30mm
18mm (11/16")						6x28.5mm	6x30mm
17mm (21/32")						6x28.5mm	6x28.5mm
16mm (5/8")					5x24mm	6x25.5mm	6x28.5mm
15mm (19/32")	5x20mm	5x22mm	5x22mm	5x24mm	5x24mm	6x25.5mm	6x25.5mm
14mm (9/16")	5x20mm	5x22mm	5x22mm	5x24mm	5x24mm	6x24mm	6x25.5mm
13mm (1/2")	5x18mm	5x20mm	5x20mm	5x22mm	5x22mm	6x24mm	6x24mm
12mm (15/32")	5x18mm	5x20mm	5x20mm	5x22mm	5x22mm	6x22.5mm	6x24mm
11mm (7/16")	5x16mm	5x18mm	5x18mm	5x20mm	5x20mm	6x22.5mm	6x22.5mm
10mm (3/8")	5x16mm	5x18mm	5x18mm	5x20mm	5x20mm	6x21mm	6x22.5mm
9mm (11/32")	5x14mm	5x16mm	5x16mm	5x18mm	5x18mm	6x21mm	6x21mm
8mm (5/16")	5x14mm	5x16mm	5x16mm	5x18mm	5x18mm		
7mm (9/32")	5x12mm	5x14mm	5x14mm	5x16mm	5x16mm		
6mm (1/4")	5x12mm	5x14mm	5x14mm	5x16mm	5x16mm		
5mm (3/16")	5x10mm	5x12mm	5x12mm	5x14mm	5x14mm		
4mm (5/32")	5x10mm	5x12mm	5x12mm	5x14mm	5x14mm		

Belt Thickness under splice (We recommend to skive the belt)